



AW135BT

1. Date
June 18, 2013
2. Firmware Version
Version 3.2 Rev 02
3. New Features
Half Duplex, Connectionless - Asynchronous Response Mode
Call Sign Support
Base and Rover Time slot synchronization
LED test support
4. Fixed Bugs
5. Known Issues and Problems
No known issues are available.